

EMC Technologies Pty Ltd

ABN 82 057 105 549 176 Harrick Road Keilor Park Victoria Australia 3042

Ph: + 613 9365 1000 Fax: + 613 9331 7455 email: melb@emctech.com.au

To: TIMCO Engineering Inc.

Attention: Certification Manager No. of pages: 1

From: Donna Lennon Date: 10th May 2007

EMC Ref: M061023_Cert_RX_INN_Class2

Subject: FCC APPROVAL – FCC ID: UWT-RX-4002-02

TIMCO job # 899AC7

Based upon our review of this application we have the following questions:

1. 731 FORM: Please provide us with a 731 form and filing for the NII portion of the device. We must apply a change in Id filing for this portion of the device as well. Thanks.

NII portion of this device is disabled. Please refer to attached revised user manual page 22, first paragraph.

- 2. Cover letter: Please add statements for compliance with 2.933(b)(3) and (b)(4):
- "(3) How the equipment bearing the modified identification differs from the original equipment."
- "(4) Whether the original test results continue to be representative of and applicable to the equipment bearing the changed identification."

Refer to revised cover letter.

3. The following file was submitted for the change in FCCID, "M061023_Cert_RX_INN_Class_2.pdf" – 19pages (no appendices page). Please explain. The same report was found for the C2PC filing, but the latter has 20 pages.

Refer to revised test report.

Regards

Donna Lennon Report Secretary

Donne Lerron

EMC Technologies Pty Ltd