



Photographs of EUT



EUT 1







Report No.:171915-07















Report No.:171915-07









SPORTON LAB.

Report No.:171915-07






SPORTON LAB.


Report No.:171915-07








Report No.:171915-07















EUT 2





















SPURTON LAB.

Report No.:171915-07












SPURTON LAB.

Report No.:171915-07














Report No.:171915-07








Report No.:171915-07







SPURTON LAB.

Report No.:171915-07








EUT 3








Report No.:171915-07

























SPURTON LAB.


Report No.:171915-07






Report No.:171915-07








Report No.:171915-07








SPURTON LAB.

Report No.:171915-07






EUT 4







Report No.:171915-07







Report No.:171915-07

















Report No.:171915-07




















Report No.:171915-07









EUT 5










Report No.:171915-07


















Report No.:171915-07




















SPURTON LAB.

Report No.:171915-07





EUT 6








Report No.:171915-07











Report No.:171915-07















SPURTON LAB.

Report No.:171915-07







Report No.:171915-07







SPURTON LAB.


Report No.:171915-07







Report No.:171915-07



SPORTON International Inc.

TEL : 886-2-2696-2468


FAX : 886-2-2696-2255

PAGE NUMBER : 84 OF 92

ISSUED DATE : Jul. 04, 2013




Report No.:171915-07







SPURTON LAB.

Report No.:171915-07









Report No.:171915-07


EUT 7





Report No.:171915-07







Report No.:171915-07

