

ReconRobotics, Inc. 7620 West 78th Street Edina, MN 55439

Phone: 952-935-5515 Toll free: 1-866-697-6267 Fax: 952-935-5508 www.reconrobotics.com

21 April 2010

American TCB 6731 Whittier Avenue McLean, VA 22101

Attn: Director of Certification

Re:

Tune up procedure for Recon Scout

FCC ID: UYXRSK2010-01

The Recon Scout presently under evaluation for certification per FCC waiver DA 10-291 requires no tune up procedure. The transmitter uses all discrete components whose frequency is fixed and cannot be adjusted, and thus there is no user or factory tuning required. The products tested are representative samples of what should be expected during production.

Sincerely, Mu Ekund

Andrew Drenner, Ph.D. Robot Systems Architect

952-935-5515 x112

952-935-5508 (fax)

andrew.drenner@reconrobotics.com