

 The Cover letter shows contact window is Jack Li, but FCC web site displays other name. Please kindly add or amend contact window into 731 Form and Cover letter.

The contact window is Jack Li, I have modified Grantee code information. The revised 731 Form has been uploaded to database.

Please provide an operational description that meets the requirements of 2.1033.
The operational description does not explain anything about the circuitry involved (i.e., please provide operational description, circuitry description of this device).

The revised operational description has been uploaded to database.

- 2. It is required to show the value on the components which are located at the RF input site. The revised schematics has been uploaded to database.
- Please kindly provide new test report of part 15C with clear test plots.

The revised Part 15C report with clear test plots has been uploaded to database.

 The test report appears to not follow FCC approved test procedures and did not clearly identify which FCC test procedures were used for FHSS devices. The approved test procedure for FHSS is found in DA 00-705.

The revised test report with correct test procedures has been uploaded to database.

 RBW set for 20dB bandwidth measurement shown on page 10 was 100KHz, but test plots showed RBW= 10KHz for measuring Occupied Bandwidth on page 11. They are not consistent. Please correct.

Sorry to make a typed error, 10KHz should be correct.

Please kindly add a Statement of 15.105 into User manual.

The revised user manual has been uploaded to database.