

Appendix E. Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : E1 of E5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR660115E

Report Template No.: BU5-FR15EWL AC MA Version 1.4





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : E2 of E5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC MA Version 1.4




Report No.: FR660115E


<Radiated Emission>

Y Plane for CDD Modes

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : E3 of E5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15EWLAC MA Version 1.4




Report No. : FR660115E

X Plane for CDD Modes

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : E4 of E5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15EWLAC MA Version 1.4




Report No.: FR660115E

X Plane for TXBF Modes

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : E5 of E5
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLAC MA Version 1.4