

Report No.: HA322304-07B

## Appendix C. Test Setup Photos


## <Battery 1 with Scanner>



**Front View** 



Left Side View



**Right Side View** 

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : C1 of C1 Report Issued Date : Aug. 14, 2013

Report Version : Rev. 01




Report No.: HA322304-07B

## <Battery 1 without Scanner>



**Front View** 



Left Side View




Right Side View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Report Issued Date: Aug. 14, 2013

Report Version : Rev. 01




## <Battery 2 with Scanner>



**Front View** 



**Left Side View** 



Right Side View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Report Issued Date: Aug. 14, 2013

Report No.: HA322304-07B

Report Version : Rev. 01