

Report No.: FG322304-07B

Appendix A. Setup Photographs


<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A1 of A3
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01




Report No. : FG322304-07B

Y Plane









SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A2 of A3
Report Issued Date : Aug. 14, 2013

Report Version : Rev. 01






Report No.: FG322304-07B

X Plane







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : A3 of A3
Report Issued Date : Aug. 14, 2013

Report Version : Rev. 01