

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : C1 of C2
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01

Report No.: FR650305A

Report Template No.: BU5-FR15CBT Version 1.1




Report No.: FR650305A


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : C2 of C2
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1