

Appendix E. Setup Photographs

<Conducted Emission>



Remote View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS3678 Page Number : E1 of E3
Report Issued Date : May 04, 2016
Report Version : Rev. 02

Report No.: FR5O0915B

Report Template No.: BU5-FR15CBT4.0 Version 1.3





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS3678 Page Number : E2 of E3
Report Issued Date : May 04, 2016
Report Version : Rev. 02

Report No.: FR5O0915B


Report Template No.: BU5-FR15CBT4.0 Version 1.3




Report No.: FR5O0915B

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS3678 Page Number : E3 of E3
Report Issued Date : May 04, 2016
Report Version : Rev. 02

Report Template No.: BU5-FR15CBT4.0 Version 1.3