

Appendix D. SAR Test Setup Photos



(SE965) Front with Holster1 **Test Separation 0 mm**



(SE965) Back with Holster1 **Test Separation 0 mm**



(SE965) Left Side with Holster1 **Test Separation 0 mm**



(SE965) Right Side with Holster1 **Test Separation 0 mm**



(SE4750SR/MR) Right Side with Holster1, Test Separation 0 mm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

Issued Date: Dec. 07, 2015 Form version. : 150415 FCC ID: UZ7TC80N0 Page D1 of D3





(SE965) Right Side with Hosltse1 + Headset 1 Test Separation 0 mm



(SE965) Right Side with Hosltse1 + Headset 2 **Test Separation 0 mm**



(SE4750SR) Right Side with Holster1 + Headset 1 **Test Separation 0 mm**



(SE4750SR) Right Side with Holster1 + Headset 2 **Test Separation 0 mm**

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

Issued Date: Dec. 07, 2015 Form version. : 150415 FCC ID: UZ7TC80N0 Page D2 of D3







(SE965/SE4750SR/MR)
Right Side with Holster2
Test Separation 0 mm

(SE965/SE4750SR/MR) Left Side with Holster2 Test Separation 0 mm

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

FCC ID: UZ7TC80N0

Issued Date : Dec. 07, 2015 Form version. : 150415

Page D3 of D3