



Appendix F. Setup Photographs

<Conducted Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : F1 of F14 Report Issued Date: Jan. 24, 2011 Report Version : Rev. 01







Side View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F2 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01




<Radiated Emission>

Antenna 1 for 4.5V



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F3 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01





Remote View

Antenna 1 for 3.3V




Front View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F4 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01





Rear View



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F5 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01






Antenna 2 for 4.5V



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F6 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01








Remote View

Antenna 2 for 3.3V



Front View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F7 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01





Rear View





Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F8 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01






Antenna 3 for 4.5V



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F9 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01





Remote View

Antenna 3 for 3.3V




Front View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F10 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01





Rear View



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F11 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01






Antenna 4 for 3.3V



Front View



Rear View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : F12 of F14 Report Issued Date: Jan. 24, 2011 : Rev. 01 Report Version




FCC RF Test Report



Remote View

Antenna 5 for 3.3V



Front View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : F13 of F14 Report Issued Date: Jan. 24, 2011 : Rev. 01 Report Version

Report No.: FR092308B





Rear View





Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : F14 of F14
Report Issued Date : Jan. 24, 2011
Report Version : Rev. 01