


Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7SB1 Page Number : D1 of D4
Report Issued Date : Sep. 03, 2012
Report Version : Rev. 01

Report No.: FA270520

Report No. : FA270520



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7SB1 Page Number : D2 of D4
Report Issued Date : Sep. 03, 2012
Report Version : Rev. 01








TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7SB1 Page Number : D3 of D4
Report Issued Date : Sep. 03, 2012
Report Version : Rev. 01

Report No. : FA270520

FCC SAR Test Report No.: FA270520

Antenna Location:

Antenna Location



Out View

In


Inner View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7SB1 Page Number : D4 of D4
Report Issued Date : Sep. 03, 2012
Report Version : Rev. 01




Report No.: FA270520


Appendix E. **Test Setup Photos**



Front of the DUT with Phantom 0 cm Gap



Back of the DUT with Phantom 0 cm Gap



Back of the EUT with Headset nugget with Headset 1 at 0 cm Gap



Back of the EUT with Headset nugget with Headset 2 at 0 cm Gap



Back of the EUT with Speaker at 0 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7SB1

Page Number : E1 of E1 Report Issued Date: Sep. 03, 2012

Report Version : Rev. 01