

## Appendix D. SAR Test Setup Photos





(SE965) Front with Holster1, Test Separation 0 mm (SE965) Back with Holster1, Test Separation 0 mm



(SE965) Left Side with Holster1 **Test Separation 0 mm** 



(SE965) Right Side with Holster1 **Test Separation 0 mm** 



(SE4750SR/MR) Right Side with Holster1 **Test Separation 0 mm** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

Issued Date: Dec. 07, 2015 FCC ID: UZ7TC80NH Page D1 of D2 Form version. : 150415





(SE965) Right Side with Holster1 + Headset 1 Test Separation 0 mm



(SE965) Right Side with Holster1 + Headset 2 **Test Separation 0 mm** 



(SE965/SE4750SR/MR) Right Side with Holster2 **Test Separation 0 mm** 



(SE965/SE4750SR/MR) Left Side with Holster2 **Test Separation 0 mm** 

TEL: 886-3-327-3456 / FAX: 886-3-328-4978

Issued Date : Dec. 07, 2015 Form version. : 150415 FCC ID: UZ7TC80NH Page D2 of D2