
2. Internal Photograph of EUT


Brand Name: Motorola / Model Name: AP-6

Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 3 of 32 Report Issued Date : Sep. 28, 2011





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 4 of 32 Report Issued Date : Sep. 28, 2011 Report Version : Rev. 02



Report No.: EP092308-07




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

: 5 of 32 Page Number Report Issued Date : Sep. 28, 2011



Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 6 of 32 Report Issued Date : Sep. 28, 2011

Brand Name: Motorola / Model Name: AP-6



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 7 of 32

Report Issued Date : Sep. 28, 2011



Report No.: EP092308-07




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

: 8 of 32 Page Number Report Issued Date : Sep. 28, 2011



Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 9 of 32 Report Issued Date : Sep. 28, 2011



Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

: 10 of 32 Page Number Report Issued Date : Sep. 28, 2011

Duran I Nigura - Matanala / Mailal Nigura - AD 6

Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 11 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02




Report No.: EP092308-07



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 12 of 32 Report Issued Date : Sep. 28, 2011






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 13 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02

Brand Name: Motorola / Model Name: AP-6



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 14 of 32 Report Issued Date : Sep. 28, 2011



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 15 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02



Report No.: EP092308-07




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

: 16 of 32 Page Number Report Issued Date : Sep. 28, 2011 Report Version : Rev. 02



Report No.: EP092308-07



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6


Page Number : 17 of 32 Report Issued Date : Sep. 28, 2011 Report Version : Rev. 02






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 18 of 32 Report Issued Date : Sep. 28, 2011 Report Version : Rev. 02



Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 19 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02



Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 20 of 32 Report Issued Date : Sep. 28, 2011

: Rev. 02

Report Version




Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 21 of 32 Report Issued Date : Sep. 28, 2011 Report Version : Rev. 02






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 22 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02




Down I Name - Materials / Madel Name - AD 0

Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 23 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 24 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02



Report No.: EP092308-07



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number


: 25 of 32 Report Issued Date : Sep. 28, 2011

Report Version

: Rev. 02



Report No.: EP092308-07




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number


: 26 of 32 Report Issued Date : Sep. 28, 2011






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 27 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 28 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 29 of 32 Report Issued Date : Sep. 28, 2011

Brand Name: Motorola / Model Name: AP-6

Page Number

Report Version

: 30 of 32

: Rev. 02

Report Issued Date : Sep. 28, 2011



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6




Report No.: EP092308-07



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6

Page Number : 31 of 32

Report Issued Date : Sep. 28, 2011 Report Version : Rev. 02



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 IC: 109AN-AP6 Page Number : 32 of 32
Report Issued Date : Sep. 28, 2011
Report Version : Rev. 02