

Appendix E. Setup Photographs

<Conducted Emission>




Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : E1 of E4
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR660115C





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : E2 of E4
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01




Report No. : FR660115C


<Radiated Emission>

Y Plane for Non-TXBF Modes

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : E3 of E4
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01




Report No.: FR660115C

X Plane for TXBF Modes

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : E4 of E4
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01