

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B1 of B6
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01



Mode 2



Mode 3



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B2 of B6
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01



<Radiated Emission>

Mode 1~15

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B3 of B6
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01





Mode 16

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B4 of B6
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01





Mode 17~22

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B5 of B6
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01






Mode 23

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B6 of B6
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01