3. Internal Photograph of EUT

Brand Name: Zebra / Model Name: TC56CJ

Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 21 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01



Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ

Page Number : 22 of 51 Report Issued Date : Dec. 22, 2016 Report Version : Rev. 01




Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ


Page Number : 23 of 51 Report Issued Date : Dec. 22, 2016 Report Version : Rev. 01

Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 24 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01


Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 25 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01



Report No.: EP672014-10




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ

Page Number : 26 of 51 Report Issued Date : Dec. 22, 2016 Report Version : Rev. 01

Report No.: EP672014-10


Brand Name: Zebra / Model Name: TC56CJ



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 27 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01



Report No.: EP672014-10




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ

Page Number : 28 of 51 Report Issued Date : Dec. 22, 2016 : Rev. 01 Report Version



Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ

Page Number : 29 of 51 Report Issued Date : Dec. 22, 2016 Report Version : Rev. 01




Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ


Page Number : 30 of 51 Report Issued Date : Dec. 22, 2016 Report Version : Rev. 01

Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 31 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01


Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 32 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01




Report No.: EP672014-10




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 33 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01

Report No.: EP672014-10




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 34 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01

Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 35 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01

Report No.: EP672014-10



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ IC: 109AN-TC56CJ Page Number : 36 of 51
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01