

802.11ac VHT20



Date: 8.NOV.2018 20:42:08

802.11ac VHT40




Date: 8.NOV.2018 21:16:16

TEL: 886-3-327-3456 Page Number : D7 of D13


MIMO <Ant. 1>





Date: 7.NOV.2018 18:09:10


802.11g



Date: 7.NOV.2018 18:11:41


TEL: 886-3-327-3456 Page Number: D8 of D13





Date: 7.NOV.2018 18:24:28


802.11n HT40



Date: 7.NOV.2018 18:34:09


TEL: 886-3-327-3456 Page Number : D9 of D13





Date: 7.NOV.2018 18:51:46

802.11ac VHT40



Date: 7.NOV.2018 19:07:25

TEL: 886-3-327-3456 Page Number : D10 of D13




FCC RADIO TEST REPORT

Report No.: FR8N0131-01C


MIMO <Ant. 2>

802.11b



Date: 7.NOV.2018 18:09:48


802.11g



Date: 7.NOV.2018 18:12:15


TEL: 886-3-327-3456 Page Number : D11 of D13

802.11n HT20



Date: 7.NOV.2018 18:25:05


802.11n HT40



Date: 7.NOV.2018 18:34:43


TEL: 886-3-327-3456 Page Number : D12 of D13

802.11ac VHT20



Date: 7.NOV.2018 18:52:18

802.11ac VHT40



Date: 7.NOV.2018 19:07:58

TEL: 886-3-327-3456 Page Number : D13 of D13