

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA Page Number : B1 of B6
Report Issued Date : Jul. 13, 2012
Report Version : Rev. 01



Mode 2 and 4



Mode 3




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA Page Number : B2 of B6
Report Issued Date : Jul. 13, 2012
Report Version : Rev. 01



<Radiated Emission>

Y Plane




Front View


Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA Page Number : B3 of B6
Report Issued Date : Jul. 13, 2012
Report Version : Rev. 01







Remote View (HF)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA Page Number : B4 of B6
Report Issued Date : Jul. 13, 2012
Report Version : Rev. 01






Z Plane

Front View

Rear View




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA Page Number : B5 of B6
Report Issued Date : Jul. 13, 2012
Report Version : Rev. 01

Report No.: FR221518-01B





Remote View (LF)

Remote View (HF)

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA Page Number : B6 of B6
Report Issued Date : Jul. 13, 2012
Report Version : Rev. 01