


# Appendix C. Setup Photographs

## <Conducted Emission>

#### Mode 1

<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C1 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834A





Report No.: FR672834A

Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C2 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01



Mode 1
<Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C3 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834A





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C4 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No. : FR672834A



Mode 2
<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C5 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834A



Report No.: FR672834A



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C6 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01



# Mode 2 <Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C7 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834A





Rear View




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C8 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834A



Mode 3
<Original test result with NFC antenna>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C9 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834A



Report No. : FR672834A



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C10 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01



Mode 3
<Terminal test result with dummy load>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C11 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834A





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C12 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01


Report No. : FR672834A




### <Radiated Emission>

### **Z** Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC75EK Page Number : C13 of C13
Report Issued Date : Sep. 29, 2016
Report Version : Rev. 01

Report No.: FR672834A