3. Internal Photograph of EUT

Brand Name: Motorola / Model Name: MC4597

Report No.: EP250901



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597 Page Number : 9 of 21 Report Issued Date : Dec. 05, 2012

Report Version : Rev. 01




Report No.: EP250901




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597

Page Number : 10 of 21 Report Issued Date : Dec. 05, 2012 Report Version : Rev. 01








TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597 Page Number : 11 of 21
Report Issued Date : Dec. 05, 2012
Report Version : Rev. 01



Report No.: EP250901




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597

Page Number : 12 of 21 Report Issued Date : Dec. 05, 2012 Report Version : Rev. 01




Report No.: EP250901



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597 Page Number : 13 of 21
Report Issued Date : Dec. 05, 2012
Report Version : Rev. 01



Report No.: EP250901



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597


Page Number : 14 of 21 Report Issued Date : Dec. 05, 2012 Report Version : Rev. 01

Report No.: EP250901



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597 Page Number : 15 of 21
Report Issued Date : Dec. 05, 2012
Report Version : Rev. 01


Report No.: EP250901



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597 Page Number : 16 of 21
Report Issued Date : Dec. 05, 2012
Report Version : Rev. 01



Report No.: EP250901




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597

: 17 of 21 Page Number Report Issued Date : Dec. 05, 2012 Report Version : Rev. 01



Report No.: EP250901




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597

: 18 of 21 Page Number Report Issued Date : Dec. 05, 2012 Report Version : Rev. 01



Report No.: EP250901



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597

Page Number : 19 of 21 Report Issued Date : Dec. 05, 2012 Report Version : Rev. 01



Report No.: EP250901




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597

Page Number : 20 of 21 Report Issued Date : Dec. 05, 2012 Report Version : Rev. 01



Report No.: EP250901



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 IC: 109AN-MC4597

Page Number : 21 of 21 Report Issued Date : Dec. 05, 2012 Report Version : Rev. 01