

Report No.: EP672014-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 43 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 44 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 45 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 46 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 47 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 48 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01


Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 49 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01



Report No.: EP672014-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K

Page Number : 50 of 53 Report Issued Date : Sep. 19, 2016 Report Version : Rev. 01



Report No.: EP672014-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K

Page Number : 51 of 53 Report Issued Date : Sep. 19, 2016 Report Version : Rev. 01



Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K

Page Number : 52 of 53 Report Issued Date : Sep. 19, 2016 Report Version : Rev. 01



Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K

Page Number : 53 of 53 Report Issued Date : Sep. 19, 2016 Report Version : Rev. 01