

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B1 of B5
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01





Mode 2



Mode 3



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B2 of B5
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01




<Radiated Emission>

Mode 1~18

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B3 of B5
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01






Mode 19

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B4 of B5
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01






Mode 20

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC55N0 Page Number : B5 of B5
Report Issued Date : Aug. 05, 2011
Report Version : Rev. 01