


Appendix E. Setup Photographs

<Conducted Emission>



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTHUBFXD Page Number : E1 of E3
Report Issued Date : Dec. 02, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No.: FR692215A







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTHUBFXD Page Number : E2 of E3
Report Issued Date : Dec. 02, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTHUBFXD Page Number : E3 of E3
Report Issued Date : Dec. 02, 2016
Report Version : Rev. 01

Report No.: FR692215A

Report Template No.: BU5-FR15CBT4.0 Version 1.3