Appendix C. Setup Photographs


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : C1 of C3
Report Issued Date : Jun. 22, 2016
Report Version : Rev. 01


Report Template No.: BU5-FG22/24/27/90 Version 1.1

Report No.: FG650305A

Report No.: FG650305A

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : C2 of C3
Report Issued Date : Jun. 22, 2016
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27/90 Version 1.1


Report No. : FG650305A

Z Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : C3 of C3
Report Issued Date : Jun. 22, 2016
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27/90 Version 1.1