

Appendix C. Setup Photographs

<Conducted Emission>




Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : C1 of C3
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report No.: FR660115A

Report Template No.: BU5-FR15CBT Version 1.1





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : C2 of C3
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 1.1




<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BT Page Number : C3 of C3
Report Issued Date : Aug. 05, 2016
Report Version : Rev. 01

Report No.: FR660115A

Report Template No.: BU5-FR15CBT Version 1.1