


Report No.: FA9O1409

Appendix E. Test Setup Photos



Right Cheek - Straight type





Right Tilted - Rotating type



Left Cheek - Rotating type



Left Tilted - Rotating type

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC3190 IC: 109AN-MC3190

: E1 of E2 Page Number Report Issued Date: Nov. 24, 2009

Report Version : Rev. 01





Report No.: FA9O1409

Face of the DUT with Phantom 0 cm Gap - Straight type

Face of the DUT with Phantom 0 cm Gap Rotating type



Face of the DUT with Phantom 0 cm Gap - Gun type

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC3190 IC: 109AN-MC3190 Page Number : E2 of E2
Report Issued Date : Nov. 24, 2009
Report Version : Rev. 01