


Appendix D. Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ

Page Number : D1 of D3 Report Issued Date: Dec. 22, 2016 Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No.: FR672014-10B





Rear View


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ Page Number : D2 of D3
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.3




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ Page Number : D3 of D3
Report Issued Date : Dec. 22, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.3

Report No.: FR672014-10B