

Report No. : FR221518-01A

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA Page Number : B1 of B4
Report Issued Date : Jul. 13, 2012
Report Version : Rev. 01



Report No.: FR221518-01A

Mode 2 and 4



Mode 3




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA Page Number : B2 of B4
Report Issued Date : Jul. 13, 2012
Report Version : Rev. 01



Report No.: FR221518-01A

<Radiated Emission>




Front View

Rear View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA Page Number : B3 of B4
Report Issued Date : Jul. 13, 2012
Report Version : Rev. 01



Report No.: FR221518-01A



Remote View (LF)

Remote View (HF)

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67NA