
## 1. External Photograph of EUT

Model Name: ES405B

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 1 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 2 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 3 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 4 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01




Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 5 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 6 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 7 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 8 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 9 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 10 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 11 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 12 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

## 2. Photograph of Accessory

Model Name: ES405B

Report No.: EP010103

## **List of Accessory:**

Specification of Accessory		
AC Adapter	Brand Name	MOTOROLA
	Model Name	IU08-2050120-WP
	Power Rating	I/P:100-240Vac, 50-60Hz, 0.2A;
		O/P: 5Vdc, 1.2A
Battery 1	Brand Name	MOTOROLA
	Model Name	82-118523-01
	Power Rating	3.7Vdc, 1540mAh, 5.70Wh
	Туре	Li-ion
Battery 2	Brand Name	MOTOROLA
	Model Name	82-118524-01
	Power Rating	3.7Vdc, 3080mAh, 11.40Wh
	Туре	Li-ion
Earphone	Brand Name	VXI
	Model Name	VR 10
	Signal Line Type	1.8 meter non-shielded cable with ferrite core
USB Cable	Brand Name	MOTOROLA
	Model Name	25-128458-01R
	Signal Line Type	1.5 meter shielded cable without ferrite core
Holster	Brand Name	MOTOROLA
	Model Name	SG-ES4021210-01R
LCD Panel	Brand Name	SAMSUNG
	Model Name	3.0"VGA PenTile
Cradle	Brand Name	MOTOROLA
	Model Name	CRD400-1000
Camera	Brand Name	MOTOROLA JABIL
	Model Name	3Mpixels

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 13 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 14 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01




Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 15 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 16 of 46 Issued Date : Mar. 18, 2010


Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 17 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 18 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 19 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



Symbol Technologies Inc.

3.7V LITHIUM ION BATTERY 3080mAh 11.40V/h
CELL ORIGIN OF CHINA. FINISHED IN CHINA.
FOR USE WITH ES400 SERIES ONLY.
WARNING: Do not disassembly, short circuit, or dispose of in fire.
CAUTION: Risk of explosion if battery is replaced by an incorrect type. Dispose of used batteries according to instructions.

P/N: 82-118524-01 Rev 02

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 20 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 21 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01



Report No.: EP010103




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 22 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 23 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 24 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 25 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 26 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 27 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 28 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01