

802.11ac VHT40



Date: 22.JAN.2019 15:43:06

802.11ac VHT80




Date: 22.JAN.2019 17:14:31

TEL: 886-3-327-3456 Page Number : D7 of D13

FCC RADIO TEST REPORT

MIMO <Ant. 1>


802.11a



Report No.: FR911104E

Date: 17.JAN.2019 20:28:31


802.11n HT20



Date: 22.JAN.2019 11:56:58


TEL: 886-3-327-3456 Page Number : D8 of D13

802.11n HT40



Date: 22.JAN.2019 15:18:32


802.11ac VHT20



Date: 17.JAN.2019 20:40:27


TEL: 886-3-327-3456 Page Number : D9 of D13

802.11ac VHT40



Date: 17.JAN.2019 20:44:36

802.11ac VHT80



Date: 17.JAN.2019 20:50:18


FAX: 886-3-328-4978

TEL: 886-3-327-3456 Page Number : D10 of D13

FCC RADIO TEST REPORT

MIMO <Ant. 2>


802.11a



Report No.: FR911104E

Date: 17.JAN.2019 20:27:12


802.11n HT20



Date: 22.JAN.2019 11:59:11


TEL: 886-3-327-3456 Page Number : D11 of D13

802.11n HT40



Date: 22.JAN.2019 15:30:06

802.11ac VHT20



Date: 17.JAN.2019 20:41:06


FAX: 886-3-328-4978

TEL: 886-3-327-3456 Page Number : D12 of D13

FCC RADIO TEST REPORT


Report No.: FR911104E

802.11ac VHT40



Date: 17.JAN.2019 20:43:59

802.11ac VHT80



Date: 17.JAN.2019 20:47:54

TEL: 886-3-327-3456 Page Number : D13 of D13