
3. Internal Photograph of EUT

Model Name: ES405B


Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 29 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 30 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01




Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 31 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 32 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01



Report No.: EP010103




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 33 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01




Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B


Page Number : 34 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 35 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01




Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 36 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 37 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01



Model Name: ES405B 30 80 20 70 60 50 01 00 1 06 08 07 09 03 10 30 20 30


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 38 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01

Report No.: EP010103




Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 39 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 40 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01



Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 41 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 42 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 43 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 44 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B Page Number : 45 of 46
Issued Date : Mar. 18, 2010
Report Version : Rev. 01

Report No.: EP010103



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ES405B IC: 109AN-ES405B

Page Number : 46 of 46 Issued Date : Mar. 18, 2010 Report Version : Rev. 01