## 3. Internal Photograph of EUT


Brand Name: Motorola / Model Name: CCHUB1

Report No.: EP2D1407



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 IC: 109AN-CCHUB1 Page Number : 6 of 12
Report Issued Date : Feb. 22, 2013
Report Version : Rev. 01

Report No.: EP2D1407




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 IC: 109AN-CCHUB1

Page Number : 7 of 12 Report Issued Date : Feb. 22, 2013

Report Version : Rev. 01


Report No.: EP2D1407



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 IC: 109AN-CCHUB1 Page Number : 8 of 12 Report Issued Date : Feb. 22, 2013

Report Version : Rev. 01


Report No.: EP2D1407



TEL: 886-3-327-3456
FAX: 886-3-328-4978
FCC ID: UZ7CCHUB1
IC: 109AN-CCHUB1


Page Number : 9 of 12
Report Issued Date : Feb. 22, 2013
Report Version : Rev. 01

Report No.: EP2D1407



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 IC: 109AN-CCHUB1 Page Number : 10 of 12
Report Issued Date : Feb. 22, 2013
Report Version : Rev. 01

Report No.: EP2D1407



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 IC: 109AN-CCHUB1 Page Number : 11 of 12
Report Issued Date : Feb. 22, 2013
Report Version : Rev. 01

Report No.: EP2D1407

## WLAN 2.4GHz & Bluetooth\_Antenna 2 <Tx / Rx>



TEL: 886-3-327-3456
FAX: 886-3-328-4978
FCC ID: UZ7CCHUB1
IC: 109AN-CCHUB1

Page Number : 12 of 12
Report Issued Date : Feb. 22, 2013
Report Version : Rev. 01