
Appendix E. Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTBRDGM Page Number : E1 of E3
Report Issued Date : Dec. 08, 2016
Report Version : Rev. 01

Report No.: FR6O0724D

Report Template No.: BU5-FR15EWLB4 Version 1.4





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTBRDGM Page Number : E2 of E3
Report Issued Date : Dec. 08, 2016
Report Version : Rev. 01

Report No.: FR6O0724D


Report Template No.: BU5-FR15EWLB4 Version 1.4

CC Test Report No.: FR600724D


<Radiated Emission>

Y Plane

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTBRDGM Page Number : E3 of E3
Report Issued Date : Dec. 08, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 Version 1.4