


# Appendix E. Setup Photographs

## <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : E1 of E5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01

Report No.: FR650305C



Report No. : FR650305C



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : E2 of E5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01




### <Radiated Emission>

### X Plane for TXBF Modes

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : E3 of E5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01


Report No.: FR650305C



Report No. : FR650305C

#### **Z Plane for Non-TXBF Modes**

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : E4 of E5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01



Report No.: FR650305C

### X Plane for Non-TXBF Modes

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET55BE Page Number : E5 of E5
Report Issued Date : Jun. 21, 2016
Report Version : Rev. 01