



Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Mode 2



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 Page Number : B1 of B3
Report Issued Date : Dec. 05, 2012
Report Version : Rev. 01


Report No.: FR250901B




<Radiated Emission>

<2.4G>

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 Page Number : B2 of B3
Report Issued Date : Dec. 05, 2012
Report Version : Rev. 01


Report No.: FR250901B




Report No.: FR250901B

<5G>





HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC4597 Page Number : B3 of B3
Report Issued Date : Dec. 05, 2012
Report Version : Rev. 01