





Single File Photographs_Internal














Report No.: 592302-06





Report No.: 592302-06





SPORTON International Inc.

TEL : 886-3-327-3456

FAX : 886-3-327-0973

PAGE NUMBER : 6 of 30

ISSUED DATE : Feb. 02, 2016










Report No.: 592302-06



SPORTON International Inc.

TEL : 886-3-327-3456


FAX : 886-3-327-0973

PAGE NUMBER : 10 of 30

ISSUED DATE : Feb. 02, 2016



Report No.: 592302-06




SPORTON International Inc.

TEL : 886-3-327-3456

FAX : 886-3-327-0973


PAGE NUMBER : 11 of 30

ISSUED DATE : Feb. 02, 2016





Report No.: 592302-06








SPURTON LAB.

Report No.: 592302-06





Report No.: 592302-06





SPORTON International Inc.

TEL : 886-3-327-3456

FAX : 886-3-327-0973

PAGE NUMBER : 16 of 30


ISSUED DATE : Feb. 02, 2016








Report No.: 592302-06








Report No.: 592302-06






Report No.: 592302-06







Report No.: 592302-06



SPORTON International Inc.

TEL : 886-3-327-3456



FAX : 886-3-327-0973

PAGE NUMBER : 23 of 30

ISSUED DATE : Feb. 02, 2016



Report No.: 592302-06




SPORTON International Inc.

TEL : 886-3-327-3456

FAX : 886-3-327-0973

PAGE NUMBER : 24 of 30



ISSUED DATE : Feb. 02, 2016







SPURTON LAB.

Report No.: 592302-06







Report No.: 592302-06







Report No.: 592302-06







Single File Antenna_Photographs

Antenna Set 1





Report No.: 592302-06


Antenna Set 3





Report No.: 592302-06

Antenna Set 10





Report No.: 592302-06



Antenna Set 11







Report No.: 592302-06







Report No.: 592302-06

Antenna Set 13






Report No.: 592302-06






Report No.: 592302-06





Report No.: 592302-06





SPURTON LAB.

Report No.: 592302-06

