


Page Number : 216 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01

Report No.: EP790120




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330K IC: 109AN-MC330K Page Number : 217 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01

Report No.: EP790120




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330K IC: 109AN-MC330K Page Number : 218 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01






Page Number : 219 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01

Report No.: EP790120



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330K IC: 109AN-MC330K Page Number : 220 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01






Page Number : 221 of 228 Report Issued Date : Nov. 06, 2017 Report Version : Rev. 01

Report No.: EP790120

Report No.: EP790120




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330K IC: 109AN-MC330K Page Number : 222 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01

Report No.: EP790120




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330K IC: 109AN-MC330K Page Number : 223 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01





Page Number : 224 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01


Report No.: EP790120



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330K IC: 109AN-MC330K Page Number : 225 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330K IC: 109AN-MC330K

Page Number : 226 of 228 Report Issued Date : Nov. 06, 2017 Report Version : Rev. 01

Report No.: EP790120

Report No.: EP790120



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330K IC: 109AN-MC330K Page Number : 227 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01

Report No.: EP790120



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330K IC: 109AN-MC330K Page Number : 228 of 228
Report Issued Date : Nov. 06, 2017
Report Version : Rev. 01