

Report No.: FR252422B

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID : UZ7ET1N2

Page Number : B1 of B4 Report Issued Date: Jun. 19, 2012 Report Version : Rev. 01





Mode 2



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET1N2 Page Number : B2 of B4
Report Issued Date : Jun. 19, 2012
Report Version : Rev. 01

Report No.: FR252422B




Report No. : FR252422B


<Radiated Emission>

Mode 1~9

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID : UZ7ET1N2

Page Number : B3 of B4 Report Issued Date: Jun. 19, 2012 Report Version : Rev. 01




Report No. : FR252422B

<Radiated Emission>

Mode 10~15

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7ET1N2 Page Number : B4 of B4
Report Issued Date : Jun. 19, 2012
Report Version : Rev. 01