
72-167783-01 Revision B January 2013









personal injury or equipment damage

WARNING! Indicates a condition or procedure that could result in

loss or equipment malfunction.

CAUTION Care is required. Disregarding a caution can result in data





situations:

NOTE Tips, hints, or special requirements that you should take note of

The following graphical alerts are used in this document to indicate notable

MOD-8132-6001S Internal Antenna Sensor Module Installation Guide

Health and Safety Recommendations Warnings for Use of Wireless Devices Please observe all warning notices with regard to the usage of wireless devices.

Potentially Hazardous Atmospheres - Fixed Installations

You are reminded of the need to observe restrictions on the use of radio devices in fuel depots, chemical plants etc. and areas where the air contains chemicals or particles (such as grain, dust, or metal powders).

Safety in Hospitals

Wireless devices transmit radio frequency energy and may affect medical electrical equipment. When installed adjacent to other equipment, it is advised to verify that the adjacent equipment is not adversely affected.

Pacemaker manufacturers recommended that a minimum of 15cm (6 inches) be maintained between a handheld wireless device and a pacemaker to avoid potential interference with the pacemaker. These recommendations are consistent with independent research and recommendations by Wireless Technology Research.

Should ALWAYS keep the device more than 15cm (6 inches) from their pacemaker

Pacemakers

Please refer to the *Declaration of Conformity* (DoC) for details of other country markings. This is available at http://www.motorola.com/doc.

Regulatory markings, subject to certification, are applied to the device signifying the radio(s) is/are approved for use in the following countries: United States, Canada, Japan, China, S. Korea, Australia, and Europe (Note 1,2).

When Motorola Solutions devices are professionally installed, the Radio Frequency Output Power will not exceed the maximum allowable limit for the country of operation.

This device is only to be used with a Motorola Solutions AP-8132 Access Point

Wireless Device Country Approvals

Any changes or modifications to Motorola Solutions equipment, not expressly approved by Motorola Solutions, could void the user's authority to operate the equipment.

Note 1: For 2.46Hz or 5GHz Products: Europe includes, Austria, Belgium, Bulgaria, Czech Republic, Cyprus, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Liechtenstein, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovak Republic, Slovenia, Spain, Sweden, Switzerland and the United Kingdom.

Note 2: Operation of the device without regulatory approval is illegal

Country Selection

Select only the country in which you are using the device. Any other selection will make the operation of this device illegal.

Frequency of Operation - FCC and IC 5 GHz Only

The use in the UNII (Unlicensed National Information Infrastructure) band 1 (5150-5250 MHz) is restricted to Indoor Use Only; any other use will make the operation of this device illegal. Industry Canada Statement

Caution: The device for the band 5150-5250 MHz is only for indoor usage to reduce potential for harmful interference to co-Channel mobile satellite systems. High power radars are allocated as primary users (meaning they have priority) of 5250-5350 MHz and 5650-5850 MHz and these radars could cause interference and/or damage to LE-LAN devices. Les utilisateurs de radars de haute puissance sont désignés utilisateurs principaux (c.-à-d., qu'ils ont la priorité) pour les bands 5250-5350 MHz et 5650-5850 MHz et que ces radars pourraient causer du brouillage et/ou des dommages aux dispositifs LAN-EL. **Avertissement:** Le dispositive fonctionnant dans la bande 5150-5250 MHz est réservé uniquement pour une utilisation à l'intérieur afin de réduire les risques de brouillage préjudiciable aux systèmes de satellites mobiles utilisant les mêmes canaux.

All Motorola devices are designed to be compliant with rules and regulations in locations where they are sold and will be labeled as required.

This device is approved under Motorola Solutions, Inc. This guide applies to Model Number KHUSB600.

Regulatory Information

Local language translations are available at the following website

http://supportcentral.motorola.com

(3)

Confirm the sensor module is operational by observing its LEDs.

RF Exposure Guidelines

Safety Information

Reducing RF Exposure - Use Properly

The device complies with internationally recognized standards covering human exposure to electromagnetic fields from radio devices. For information on "International" human exposure to electromagnetic fields refer to the Motorola/Symbol *Declaration of Conformity* (DoC) at

Radiation Exposure Statement:

NOTE IMPORTANTE: (Pour l'utilisation de dispositifs mobiles)

Cet équipement est conforme aux limites d'exposition aux rayonnements IC établies pour un environnement non contrôlé. Cet équipement doit être installé et utilisé avec un minimum de 30 cm de distance entre la source de rayonnement et votre corps.

Other Medical Devices

Please consult your physician or the manufacturer of the medical device, to determine if the operation of your wireless product may interfere with the medical device.

If you have any reason to suspect that interference is taking place, turn OFF your

Should use the ear furthest from the pacemaker to minimize the potential for

Should not carry the device in a breast pocket.

when turned 0N

Persons with Pacemakers:





MOTOROLA

 \equiv

2



(9)

Only operate the device in accordance with the instructions supplied.

International

motorola.com/doc. Co-located statement US and Canada

To comply with FCC RF exposure compliance requirement, the antenna used for this transmitter must not be co-located or operating in conjunction with any other transmitter/antenna except those already approved in this filling.

This equipment complies with IC radiation exposure limits set forth foa na uncontrolled environment. This equipment should be installed and operated with minimum distance 30cm between the radiator and your body.

Déclaration d'exposition aux radiations:

(2)

MOTOROLA SOLUTIONS INC. 1303 E. ALGONQUIN ROAD

SCHAUMBURG, IL 60196

http://www.motorolasolutions.com

Width

Length 6.0 in / 15.24 cm 2.5 in /6.3 cm

Weight Height 0.270 lb / 0.123 kg 1.625 in / 4.127 cm

Radio Technology 2x2 MIM0 802.11 a/b/g/n

The MOD-8132-6001S sesnsor module is plenum rated

Storage Temperature

Installing the MOD-8132-6001S Internal Antenna Sensor Module

Align the tabs on the sensor module with the corresponding slots on the Access Point.
Securely attach the sensor module to the Access Point.

Read all installation instructions and site survey reports, and verify correct equipment installation before connecting the MOD-8132-6001S sensor module.

Remove jewelry and watches before installing this equipment.

Verify any device connected to this unit is properly wired and grounded.

AP-8132's radio coverage area. The output of the sensor's detection mechanisms are

reported within the ADSP system. **Document Conventions**

wireless security sensing mechanisms, allowing monitoring and reporting within the

model access point for use with the Motorola Solutions ADSP platform. It provides

The MOD-8132-6001S sensor module is a USB sensor extension to the AP-8132

ntroduction

equipment operation specifications.

Precautions

Before installing an MOD-8132-6001S sensor module, verify the following

You are using one of the correctly rated power solutions for the AP-8132 access point:

AP-PSBIAS-2P3-ATR power injector

PWRS-14000-247R external power supply

• Motorola Solutions recommends you do not to install the MOD-8132-6001S in wet or dusty

ullet Verify the environment has a continuous temperature range between 0° C to 50° C.

Specifications

Operating Temperature 0° to 50° celsius / 35° to 122° farenheit -20° to 80° celsius / -4° to 176° farenheit

Warnings

Verify there is adequate ventilation around the device, and that ambient temperatures meet

Radio Frequency Interference Requirements - FCC



This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and cardiate radio frequency energy and, if not installed and used in accordance with the insuructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause hamful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna
- Increase the separation between the equipment and receiver
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected
 - Consult the dealer or an experienced radio/TV technician for help.

Radio Transmitters (Part 15)

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. The use of 5 GHz WLAN's, for use in the US , have the following restrictions:

Notched Band 5.60 - 5.65 GHz

Radio Frequency Interference Requirements - Canada

This Class B digital apparatus complies with Canadian ICES-003.

Cet appareil numérique de la classe B est conforme à la norme NMB-003 du Canada.

Radio Transmitters

For RLAN Devices

The use of 5 GHz RLAN's, for use in Canada, have the following restrictions:

Ce dispositif est conforme à la norme CNR-210 d'Industrie Canada applicable aux appareils radio exempts de licence. Son fonctionnement est sujet aux deux conditions suivantes. (1) le dispositif ne doit pas produire de brouillage préjudiciable, et (2) ce dispositif doit accepter tout brouillage reçu, y compris un brouillage susceptible de provoquer un fonctionnement indésirable.

6

Label Marking: The Term "IC." before the radio certification only signifies that Industry Canada technical specifications were met.



Marking and European Economic Area (EEA)

The use of 2.4GHz RLAN's, for use through the EEA, have the following restrictions:

- Maximum radiated transmit power of 100 mW EIRP in the frequency range 2.400
 - Italy requires a user license for outside usage. -2.4835 GHz.

Statement of Compliance

Motorola Solutions hereby declares that this device is in compliance with all the applicable Directives, 1999/5/EC. A Declaration of Conformity may be obtained from

http://www.motorola.com/doc.

Japan (VCCI) - Voluntary Control Council for Interference

Class B ITE

らの採掘な、病療処理染態の異次部等自力表別環境(ACCI)の基当の基づくクラスB循数技術染質のす。この染料な、液度過程の使用することを回路としてウオサゲ、この染料がテプナやテアビデョン製造機の通路して使用されると、受資料等を引き返こすことがあります。製造機関を引き返こすことがあります。製造機関を引き返こすことがあります。製造機関を引き返こすことがあります。

Korea Warning Statement for Class B ITE

사용자안내문	용(B글) 전자파적합기기로서 주	가장에서 사용하는 것을 목적으로 하며, 모든	₹ 3
80 80 80	R은 기기	(가정용 방송왕신기자과)	

Other Countries

Australia

Use of 5GHz RLAN's in Australia is restricted in the following band 5.50 – 5.65GHz.

8

Brazil

(10)

Declarações Regulamentares para AP-8132 - Brasil

Polski: Klienci z obszaru Unii Europejskiej: Produkty wycofane z eksploatacji należy zwróciæ do firmy Motorola w celu ich utylizacji. Informacje na temat zwrotu produktów znajduj[:] siê na stronie

internetowej http://www.motorola.com/recycling/weee.

Eesti: EL klientidele: kõik tooted tuleb nende eluea lõppedes tagastada taaskasutamise eesmärgi'

Motorola'ile. Lisainformatsiooni saamiseks toote tagastamise kohta külastage palun aadressi

http://www.motorola.com/recycling/weee.

Magyar: Az EU-ban vásárlóknak: Minden tönkrement terméket a Motorola vállalathoz kell

eljuttatni újrahasznosítás céljából. A termék visszajuttatásának módjával kapcsolatos tudnivalókért látogasson el a http://www.motorola.com/recycling/weee weboldalra.

Čeština: Pro zákazníky z EU: Všechny produkty je nutné po skoněení jejich životnosti vrátit spoleěnosti Motorola k recyklaci. Informace o způsobu vrácení produktu najdete na webové stránce: http://www.motorola.com/recycling/weee.

mesmo de estações do mesmo tipo, e não pode causar interferência a sistemas operando em caráter primário. Para maiores informações sobre ANATEL consulte o site: www.anatel.gov.br. Nota: A marca de certificação se aplica ao Transceptor, modelo AP-8132. Este equipamento opera em caráter secundário, isto é, não tem direito a proteção contra interferência prejudicial

Este equipo cumple con la Resolución No 403 de 2008, de la Subsecretaria de telecomunicaciones, relativa a radiaciones electromagnéticas



Taiwan

机分配的过程形式装置的图据分据

第十二年 第四时运输行输入机场的建步振荡器,中途许问,机理、高铁机械的电池分子保持回线阻挠率,包含时间将规模照明设计之中可以达额。

udtjent. Læs oplysningerne om returnering af produkter på: http://www.motorola.com/recycling/

Ελληνικά: Για πελάτες στην Ε.Ε.: Όλα τα προϊόντα, στο τέλος της διάρκειας ζωής τους, πρέπει να επιστρέφονται στην Μοτονοία για ανακύκλωση. Για περισσότερες πληροφορίες σχετικά με την επιστροφή ενός προϊόντος, επισκεφθείτε τη διεύθυνση http:// www.motorola.com/recycling/weee στο Διαδίκτυο.

Dansk: Til kunder i EU: Alle produkter skal returneres til Motorola til recirkulering, når de er

Suomi: Asiakkaat Euroopan unionin alueella: Kaikki tuotteet on palautettava kierrätettäväksi

Motorola-yhtiöön, kun tuotetta ei enää käytetä. Lisätietoja tuotteen palauttamisesta on

osoitteessa http://www.motorola.com/recycling/weee.

Svenska: För kunder inom EU: Alla produkter som uppnått sin livslängd måste returneras till

Motorola för återvinning. Information om hur du returnerar produkten finns på http://

www.motorola.com/recycling/weee.

Matti: Ghal klijenti fI-UE: il-prodotti kollha li jkunu waslu fl-ahhar tal-hajja ta' I-użu taghhom, iridu jigu rritornati ghand Motorola ghar-riciklagg. Ghal aktar taghrif dwar kif ghandek tirritorna I-prodott, jekk joghgbok zur: http://www.motorola.com/recycling/weee.

Românesc: Pentru clienții din UE: Toate produsele, la sfârșitul duratei lor de funcționare, trebuie returnate la Motorola pentru reciclare. Pentru informații despre returnarea produsului accesați: http://www.motorola.com/recycling/weee.

哲森

低的坚约指指指之使用不得是推到各位企业及干损合法通信,经验设有干损现象时,成立即移用。社交甚至其干部的方 等的 1978年,继续指挥进步中推入电视部通信。 李元章 1978年,继续指挥进步中推入电视部通信。 每户国际指挥组织的形态化设置结构工程,学学及解释压用或程度作用整合指入干部。

在8.5年8.8 茅建湖班区港岸之南南部西部南部东海,园安村之市田

Thailand

เครื่องโทรคมนาคมและอุปกรณ์นี้ มีความสอดคล้องตามข้อกำหนดของ กทร.

6)

(11)

Slovenski: Za kupce v EU: vsi izdelki se morajo po poteku življenjske dobe vmiti podjetju Motorola za reciklažo. Za informacije o vra ilu izdelka obiš ite: http://www.motorola.com/recycling/weee. Slovenčina: Pre zákazníkov z krajín EU: Všetky výrobky musia byť po uplynutí doby ich

životnosti vrátené spoločnosti Motorola na recykláciu. Bližšie informácie o vrátení výrobkov

Lietuvių: ES vartotojams: visi gaminiai, pasibaigus jų eksploataojjos laikui, turi būti grąžinti utilizuoti į kompaniją "Motorola". Daugiau informacijos, kaip grąžinti gaminį, rasite: http:// www.motorola.com/recycling/weee.

Latviešu: ES klientiem: visi produkti pēc to kalpošanas mūža beigām ir jānogādā atpakaļ Motorola otrreizējai pārstrādei. Lai iegūtu informāciju par produktu nogādāšanu Motorola, lūdzu, skatiet: http://www.motorola.com/recycling/weee.

Türkçe: AB Müşterileri için: Kullanım süresi dolan tüm ürünler geri dönüştürme için Motorola'ya iade edilmelidir. Ürünlerin nasıl iade edileceği hakkında bilgi için lütfen şu adresi ziyaret edin: http://www.motorola.com/recycling/weee

Français: Clients de l'Union Européenne: Tous les produits en fin de cycle de vie doivent être retournés à Motorola pour recyclage. Pour de plus amples informations sur le retour de produits, consultez : http://www.motorola.com/recycling/weee.

English: For EU Customers: All products at the end of their life must be returned to Motorola for

Waste Electrical and Electronic Equipment (WEEE)

recycling. For information on how to return product, please go to: http://www.motorola.com/

recycling/weee

Español: Para clientes en la Unión Europea: todos los productos deberán entregarse a Motorola al final de su ciclo de vida para que sean reciclados. Si desea más información sobre cómo devolver un producto, visite: http://www.motorola.com/recycling/weee.

грябва да се връщат на Motorola за рециклиране. За информация относно връщането на продукти, моля отидете на адрес: http://www.motorola.com/recycling/weee

Bulgarish: За клиенти от ЕС: След края на полезния им живот всички продукти

Deutsch: Für Kunden innerhalb der EU: Alle Produkte müssen am Ende ihrer Lebensdauer zum

Recycling an Motorola zurückgesandt werden. Informationen zur Rücksendung von Produkten finden Sie unter http://www.motorola.com/recycling/weee.

Italiano: per i clienti dell'UE: tutti i prodotti che sono giunti al termine del rispettivo ciclo di vita devono essere restituiti a Motorola al fine di consentirne il riciclaggio. Per informazioni sulle

modalità di restituzione, visitare il seguente sito Web: http://www.motorola.com/recycling/

weee.

lederlands: Voor klanten in de EU: alle producten dienen aan het einde van hun levensduur naar

www.motorola.com/recycling/weee

00 1111

Motorola te worden teruggezonden voor recycling. Raadpleeg http://www.motorola.com/

recycling/weee voor meer informatie over het terugzenden van producten.

Português: Para clientes da UE: todos os produtos no fim de vida devem ser devolvidos à Motorola para reciclagem. Para obter informações sobre como devolver o produto, visite: http://

Turkish WEEE Statement of Compliance

EEE Yönetmeliğine Uygundur

(13)

Motorola Solutions Support Center

If you have a problem with your equipment, contact support for your region. When contacting Motorola Solutions support, please provide the following Contact information is available at: http://motorolasolutions.com/support.

- Serial number of the unit
- Model number or product name
- Software type and version number

limits set forth in support agreements. If you purchased your product from a Motorola Solutions business partner, contact that business partner for support. Motorola Solutions responds to calls by e-mail, telephone, or fax within the time

Customer Support Web Sites

The Motorola Solutions Support Central Web site, located at:

http://supportcentral.motorola.com/

provides information and online assistance including developer tools, software downloads, product manuals and online repair requests.

http://supportcentral.motorola.com/support/product/manuals.do

Obtain additional information by contacting Motorola Solutions at:

General Information

Telephone (North America): 1-800-722-6234

Website: http://www.motorolasolutions.com

Telephone (International): +1-631-738-5200

(14)

(12)