


Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 Page Number : 1 of 3

Report Issued Date : Feb. 22, 2013 Report Version : Rev. 01

Report No.: FR2D1407B




Report No.: FR2D1407B

<Radiated Emission>

2.4G

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 Page Number : 2 of 3
Report Issued Date : Feb. 22, 2013

: Rev. 01

Report Version



Report No. : FR2D1407B

5G

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7CCHUB1 Page Number : 3 of 3
Report Issued Date : Feb. 22, 2013

Report Version : Rev. 01