






Photographs of EUT

Model No.: AP-7532




























PAGE NUMBER : 3 OF 19
ISSUED DATE : Oct. 08, 2015











SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 4 OF 19
ISSUED DATE : Oct. 08, 2015













PAGE NUMBER : 5 OF 19
ISSUED DATE : Oct. 08, 2015




















SPORTON International Inc.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 PAGE NUMBER : 7 OF 19
ISSUED DATE : Oct. 08, 2015






















PAGE NUMBER : 9 OF 19
ISSUED DATE : Oct. 08, 2015






































PAGE NUMBER : 13 OF 19 ISSUED DATE : Oct. 08, 2015











PAGE NUMBER : 14 OF 19
ISSUED DATE : Oct. 08, 2015











PAGE NUMBER : 15 OF 19
ISSUED DATE : Oct. 08, 2015





























PAGE NUMBER : 18 OF 19
ISSUED DATE : Oct. 08, 2015







PAGE NUMBER : 19 OF 19
ISSUED DATE : Oct. 08, 2015