



Appendix A. Setup Photographs

Antenna 7 for 4.5V



LF



HF

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6

Page Number : A1 of A4 Report Issued Date: Oct. 30, 2012 : Rev. 01 Report Version





Front View





Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : A2 of A4
Report Issued Date : Oct. 30, 2012
Report Version : Rev. 01






Antenna 7 for 3.3V

LF





HF

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : A3 of A4
Report Issued Date : Oct. 30, 2012
Report Version : Rev. 01





Front View





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7AP6 Page Number : A4 of A4
Report Issued Date : Oct. 30, 2012
Report Version : Rev. 01