3. Internal Photograph of EUT

Brand Name: Zebra / Model Name: DS8178

Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178 Page Number : 7 of 21
Report Issued Date : Sep. 14, 2016

Report Version : Rev. 01

Report No.: EP680207




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178 Page Number : 8 of 21
Report Issued Date : Sep. 14, 2016

Report Version : Rev. 01



Report No.: EP680207




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178

Page Number : 9 of 21


Report Issued Date : Sep. 14, 2016 Report Version : Rev. 01

Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178 Page Number : 10 of 21
Report Issued Date : Sep. 14, 2016
Report Version : Rev. 01


Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178 Page Number : 11 of 21
Report Issued Date : Sep. 14, 2016
Report Version : Rev. 01




Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178


Page Number : 12 of 21 Report Issued Date : Sep. 14, 2016 Report Version : Rev. 01

Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178 Page Number : 13 of 21
Report Issued Date : Sep. 14, 2016
Report Version : Rev. 01


Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178 Page Number : 14 of 21
Report Issued Date : Sep. 14, 2016
Report Version : Rev. 01




Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178

Page Number : 15 of 21 Report Issued Date : Sep. 14, 2016 Report Version : Rev. 01


Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178 Page Number : 16 of 21
Report Issued Date : Sep. 14, 2016
Report Version : Rev. 01




Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178 Page Number : 17 of 21
Report Issued Date : Sep. 14, 2016
Report Version : Rev. 01


Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178 Page Number : 18 of 21
Report Issued Date : Sep. 14, 2016
Report Version : Rev. 01



Report No.: EP680207




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178

Page Number : 19 of 21 Report Issued Date : Sep. 14, 2016 Report Version : Rev. 01




Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178

Page Number : 20 of 21 Report Issued Date : Sep. 14, 2016 Report Version : Rev. 01

Report No.: EP680207



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7DS8178 IC: 109AN-DS8178

Page Number : 21 of 21 Report Issued Date : Sep. 14, 2016 Report Version : Rev. 01