External Photograph of EUT 1.

Brand Name: Zebra / Model Name: TC510K

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K

Page Number : 1 of 53 Report Issued Date : Sep. 19, 2016

Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 2 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: Zebra / Model Name: TC510K

Report No.: EP672014-01

Specification of Accessory		
Adapter 1 (5V/2.5A)	Brand Name	Zebra
	Model Number	SAWA-65-20005A
Adapter 2 (5V/1.2A)	Brand Name	Zebra
	Model Number	PS000081A01
Headset Jumper 1	Brand Name	Zebra
	Part Number	CBL-TC51-HDST25-01
Headset Jumper 2	Brand Name	Zebra
	Part Number	CBL-TC51-HDST35-01
Battery	Brand Name	Zebra
	Part Number	BT-000314-01
2.5mm Earphone	Brand Name	Zebra
	Part Number	HDST-25MM-PTVP-01
3.5mm Earphone	Brand Name	Zebra
	Part Number	HDST-35MM-PTVP-01
Trigger Handle	Brand Name	Zebra
	Part Number	TRG-TC51-SNP1-01
USB cable	Brand Name	Zebra
	Part Number	CBL-TC51-USB1-01
Soft Holster	Brand Name	Zebra
	Part Number	SG-TC51-HLSTR1-01
Exoskeleton	Brand Name	Zebra
	Part Number	SG-TC51-EX01-01
Hand strap	Brand Name	Zebra
	Part Number	SG-TC51-BHDSTP1-03

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 3 of 53
Report Issued Date : Sep. 19, 2016

Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 4 of 53

Report Issued Date : Sep. 19, 2016 Report Version : Rev. 01

Report No.: EP672014-01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 5 of 53 Report Issued Date : Sep. 19, 2016

Report Version : Rev. 01

Report No.: EP672014-01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 6 of 53

Report Issued Date : Sep. 19, 2016 Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 7 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01


Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 8 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01



Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K

Page Number : 9 of 53 Report Issued Date : Sep. 19, 2016

: Rev. 01 Report Version

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 10 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 11 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 12 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 13 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 14 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 15 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 16 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 17 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 18 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01

Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 19 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01



Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K

Page Number : 20 of 53 Report Issued Date : Sep. 19, 2016 : Rev. 01 Report Version



Report No.: EP672014-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC510K IC: 109AN-TC510K Page Number : 21 of 53
Report Issued Date : Sep. 19, 2016
Report Version : Rev. 01