


Appendix E. Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTHUBFXD Page Number : E1 of E3
Report Issued Date : Dec. 08, 2016
Report Version : Rev. 01

Report No.: FR692215D

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.4





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTHUBFXD Page Number : E2 of E3
Report Issued Date : Dec. 08, 2016
Report Version : Rev. 01

Report No.: FR692215D

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.4




<Radiated Emission>

X Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MPACTHUBFXD Page Number : E3 of E3
Report Issued Date : Dec. 08, 2016
Report Version : Rev. 01

Report No.: FR692215D

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.4