


Appendix D. Setup Photographs

<Conducted Emission>



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ Page Number : D1 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report No.: FR672014-10F

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ Page Number : D2 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC56CJ Page Number : D3 of D3
Report Issued Date : Jan. 04, 2017
Report Version : Rev. 01

Report No.: FR672014-10F

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5