


Appendix E. Setup Photographs

<Conducted Emission>

Mode 1

Original Test



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E1 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812E





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E2 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812E





Terminal Test



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E3 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01








TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E4 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812E



Mode 2
Original Test



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E5 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E6 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL AC MA Version 1.4

Report No.: FR661812E





Terminal Test



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E7 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E8 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812E



Mode 3
Original Test



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E9 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E10 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812E





Terminal Test



Remote View

Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E11 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812E







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E12 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01


Report No.: FR661812E



<Radiated Emission>

Y Plane with Earphone 1

LF







SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E13 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812E



Y Plane with Earphone 2

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E14 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01

Report No.: FR661812E



Y Plane with Notebook

LF



HЕ




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E15 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01



Z Plane with Earphone 1

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC700J Page Number : E16 of E16
Report Issued Date : Aug. 04, 2016
Report Version : Rev. 01