


Report No.: FR320416B

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67ND Page Number : B1 of B3
Report Issued Date : Mar. 22, 2013
Report Version : Rev. 01




Report No.: FR320416B


<Radiated Emission>

<X Plane for 2.4GHz>

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67ND Page Number : B2 of B3
Report Issued Date : Mar. 22, 2013
Report Version : Rev. 01




<Radiated Emission>

<Z Plane for 5GHz>

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC67ND Page Number : B3 of B3
Report Issued Date : Mar. 22, 2013
Report Version : Rev. 01

Report No.: FR320416B