3. Internal Photograph of EUT


Brand Name: Zebra / Model Name: FX9600

Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 17 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 18 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 19 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 20 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01



Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 21 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01




Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600


Page Number : 22 of 45 Report Issued Date : Nov. 02, 2017 Report Version : Rev. 01

Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 23 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01


Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 24 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01




Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 25 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01



Report No.: EP751510





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 26 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 27 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 28 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 29 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 30 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01


Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600

Page Number : 31 of 45 Report Issued Date : Nov. 02, 2017 Report Version : Rev. 01


Report No.: EP751510



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 32 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 33 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01


Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 34 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01




Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 35 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 36 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 37 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 38 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 39 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 40 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 41 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 42 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 43 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 44 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01

Report No.: EP751510



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7FX9600 IC: 109AN-FX9600 Page Number : 45 of 45
Report Issued Date : Nov. 02, 2017
Report Version : Rev. 01